


## LYNK Quick DEX Guide

The **LYNK** telemeter supports the Quick DEX feature, allowing you to easily perform a service DEX by using the device screen.

### To Perform a Quick DEX:

1. Make sure that the **LYNK** is on the main screen.
2. Tap 5 times on the area of the screen highlighted below:
3. Tap “**Service DEX**”

**LYNK Quick DEX:** Full Size and Overlay



**Quick Dex Areas:** Full Size Model (right), Overlay Model (left)

The Service DEX will display the result after the DEX is completed. For questions regarding the Quick DEX feature or for training, contact *LYNK Support*.