

LYNK Quick Reference Guide

Pre-Installation Checklist:

Before installing a new LYNK Telemeter, you will need the following:

1. Information:

To register the telemeter, you will need your:

1. **Operator ID**
2. **Operator PIN**
3. **Machine Asset ID**

For help verifying your Operator ID and PIN, contact *LYNK Support*.

2. Equipment:

1. **LYNK Telemeter**
2. **Cabling** included in LYNK Telemeter Box (MDB cable, DEX cable, etc.)

Some machines require additional cables before installation, such as the *DEX Adapter Kit*, which is needed when using an OLD I/O board LYNK Telemeter on a *Vendo*, an *AP* machine with an SL / ST board, or an *AMS Sensit 1 / 2 / 3*.

Before ordering cables from the [GlobalConnect Marketplace](#) , please confirm your machine's cabling requirements on the [LYNK Vending Machine Compatibility List](#).

3. Tools: Wrench to fasten antennas, cable ties, and LYNK Payment Options sticker.



LYNK Ports & Connections



Technical Support Site



LYNK Support Videos